US ERA ARCHIVE DOCUMENT

UNIT LOG	1. Incident Name		2. Date Prepared	3. Time Prepared	
	Kalamazoo River/Enbridge Oil Spill 12/18/20		12/18/2012	1910	
4. Unit Name/Designators	5. Unit Leader (Name and Position)			6. Operational Period	
Situation Unit	Mindy Luetke, Planning Section Chief			0700, 12/17/2012 – 1645, 12/17/2012	
7.	Personnel Roster Assigned				
Name		ICS Position	Home Base		
Dan Zahner		Situation Unit	St. Louis, MO		
8. Activity Log					
Time	Major Events				

0730 River Status

- MP 5.00 to MP 5.25(C0.4 Boat Launch) RDB: Random streamers of sheen and tar globs observed. Not enough to warrant a sheen response.
- MP 5.25 to MP 5.5 LDB: Random streamers of sheen and oil globules observed. Sheen response called in and sweep conducted
- MP 5.60 to control point RDB: Few streamers of sheen and oil globules observed. Not enough to warrant a response.
- MP 5.63 LDB: Few streamers of sheen and oil globules observed. Not enough to warrant a response.
- MP 5.65 (Control Point): Few streamers of sheen and oil globules observed. Not enough to warrant a response.
- MP 5.55 RDB (Former submerged oil location): Few sheen streamers and oil globules observed. Not enough to warrant a sheen response.
- MP 8.50 L1: Not visited today.
- · MP 8.50 L2: Not visited today.
- MP 8.75 R1: Not visited today.
- MP 10.75 LDB: Not visited today.
- MP 11.79 LDB: Not inspected today.
- · C5 Boat Launch (MP 15.00): No sheen or oil globules observed.
- MP 15.00 (Mill Ponds): Random sheen and oil globules observed along RDB from MP 15.00 to MP 15.25 (South Mill Pond.) Not enough to warrant a sheen response.
- MP 21.50 RDB: No sheen or oil globules observed.
- MP 23.15 RDB: No sheen or oil globules observed.
- MP 24.75 LDB: No sheen or oil globules observed.
- MP 26.25 LDB: No sheen or oil globules observed.
- MP 36.25 LDB: Some sheen observed, but no oil globules. Did not appear to be the same as Line 6B oil.
- MP 36.50 RDB: Random streamers and spots of sheen and oil globules observed. Not enough to warrant a sheen response.
- · Delta: No sheen observed.
- Morrow Lake North Cove: Random spots of sheen and oil globules observed. Not enough to warrant a sheen response.
- Morrow Lake South Cove: Random streamers of sheen and oil globules observed. Not enough to warrant a sheen response.
- Rowe Island: Few random streamers of sheen and oil globules observed. Not enough to warrant a sheen response.

1640 Return to ICP. End of field day.

ICS214

9. Prepared by (Name and Position)

Dan Zahner, Situation Unit, USEPA-START